



PRECISION 2.92MM WARNING





The Precision 2.92mm microwave output port is easily damaged!

Because SMA is only rated to 26GHz this device features a 40GHz precision 2.92mm RF port. 2.92mm is **NOT** mechanically identical to SMA! An adapter is required.

Take extra care when mating a cable or connector to this port, as it is expensive and extremely difficult to replace. Make sure the connectors are perfectly centered and parallel while beginning to tighten.

SMA cables can DESTROY the RF output port!



Please contact us if you have any questions! support@dsinstruments.com

