



2.92MM PORT WARNING





The Precision 2.92mm microwave output port is easily damaged!

Take extra care when mating a cable or connector to this port, as it is expensive and difficult to replace. Make sure the connectors perfectly centered and parallel while beginning to tighten.

This port is rated to 40GHz, and is compatible with SMA and precision APC 3.5mm.



